



Jazz UltraTab C1059-HL Headphone Jack Replacement

Written By: Tim Poe



INTRODUCTION


This guide will guide the user to effectively remove and replace the headphone jack. This replacement will take 15-20 minutes. However, if the guide is followed to the letter, the task will be accomplished with minimal damage to the device.

Step 1 — Headphone Jack




- Start by removing the four screws, two at the top and two at the bottom of the device.

Step 2





- Remove the back panel.
- Place the device screen down on the table.

Step 3




- First to remove the battery.
- Using a solder iron, remove the wires connecting the battery to the motherboard.

Step 4



- Now we have to remove the mother board.
- Remove the screw attaching the motherboard to the back panel.

Step 5



- The Headphone jack is attached to the mother you will then need to replace the whole mother board.
- The Headphone jack is within the black circle on the picture.
- One obtained a new motherboard, use these steps in reverse to reassemble the device.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-24 04:00:27 PM.